




Cabin #6 at Camp Moses Merrill



Looking back up the road leading to the cabin.



Fixing the door molding to prevent drafts...and mice!



Staining the trim. Before (l) and after (r)



Sweeping the floor after sanding the old paint.



Ready for a new coat of paint.

Take a trip to Camp Merrill to see the cabin for yourself! Or visit the website at <http://www.campmerrill.com/>.